

AT ABOUT 8:45. MAY HAVE BEEN
ONE OF THE PLANES AT THE WORLD
TRADE CENTER. 7 HRS.

13 SEP '01 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE. BEGAN HAND MUCKING WASTE
ROCK AND DIRT OFF THE LOWER
PART OF THE OUTCROP. 7 HRS.

14 SEP '01 EAST VEIN
FINISHED HAND MUCKING AND SPREAD
THE MUCK WITH THE EIMCO. DRILLED
HOLES AND WEDGED OUT F/W ROCK.
DELAYED BY FIRST REAL RAIN OF
THE SUMMER. 4 HRS.

---46---

17 SEP '01 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE AND F/W ROCK. 7 HRS.

19 SEP '01 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE AND F/W ROCK. THE OIL
BOTTLE HOSE BURST. HAD TO
SCROUNGE THRU THE GARAGE TO
FIND ANOTHER ONE. 7 HRS.

21 SEP '01 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE AND F/W ROCK. HAD TO
REPLACE THE AIR HOSE. 7 HRS.

24 SEP '01 EAST VEIN
FINISHED WEDGING OUT HOLES
THAT WERE DRILLED FRIDAY.
DRILLED A NEW GROUP OF HOLES,
QUIT AT 2:30 DUE TO RAIN.
6 HRS.

25 SEP '01 EAST VEIN
WEDGED OUT ORE. SAVED SOME
NICE PIECES FOR THE SHOP.
4 HRS.

26 SEP '01 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE. STARTING ON A HIGHER
LEVEL. 7 HRS.

27 SEP '01 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE. 7 HRS.

28 SEP '01 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE. 7 HRS.

--- 52 ---

1 OCT '01 EAST VEIN
WEDGED OUT HOLES FROM FRIDAY.
DRILLED A NEW SET OF HOLES.
WASHED OFF THE ORE. CAME BACK
AFTER DARK TO LAMP THE OUTCROP.
THE WILLEMITE IN PART OF IT HAS
GRADED INTO TEPHROITE, THAT
IS NOT GOOD ENOUGH TO MINE.
4 HRS.

3 OCT '01 EAST VEIN
HAND MUCKED DRILL CUTTINGS AND
FINE MUCK OFF THE LOWER PART
OF THE OUTCROP. DRILLED HOLES
AND WEDGED OUT ORE. 7 HRS.

4 OCT '01 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE. 7 HRS.

5 OCT '01 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE. 7 HRS.

8 OCT '01 EAST VEIN

WEDGED OUT ORE USING HOLES FROM FRIDAY. HANDMUCKED FINES OFF THE FOOTWALL.

DRILLED HOLES AND WEDGED OUT FOOTWALL ROCK. REMOVING THIS ROCK WILL OPEN UP THE NICE ORE BEHIND IT. MOVED THE WATER OUTLET. THIS WILL MAKE IT EASIER TO DRAIN THE WATER HOSE DURING COLD WEATHER. 7 HRS.

9 OCT '01 EAST VEIN

DRILLED HOLES AND WEDGED OUT F/W ROCK AND CONTACT ORE. STARTED DRILLING THE GOOD ORE BUT THE AIR HOSE BURST. 6 HRS

HELPED DICK BOSTWICK WEIGH AND LOAD ORE IN DRUMS. IT IS ORE I GOT LAST YEAR FROM THE EAST VEIN TUNNEL. HE PAID ME FOR 2 HR.

11 OCT '01

EAST VEIN

FOUND A REPLACEMENT FOR THE BAD AIR HOSE. DRILLED HOLES AND WEDGED OUT ORE. WASHED OFF MUD ZONE BOULDERS EXPOSING JEFFERSONITE XLS.
7 HRS.

--- 45 HRS ---

15 OCT '01

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE. DRILLED A DOUBLE ROW OF DOWN HOLES WITH THE SMALL BIT. 7 HRS.

16 OCT '01

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE. DID A LOT OF HAND MUCKING TO EXPOSE A LOWER ROCK LEDGE.
7 HRS.

17 OCT '01

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE.
6 HRS.

19 OCT '01

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE. HANDMUCKED TO REVEAL ORE FARTHER SOUTH. NOW HAVE TO DRAIN THE WATER HOSE EVERY NITE TO AVOID FREEZING. 7 HRS.

23 OCT '01 EAST VEIN
WEDGED OUT HOLES FROM FRIDAY.
BARRED OUT A LOT OF HEAVILY
ALTERED ORE TO GET AT THE
GOOD ORE AT THE SOUTH END
OF THE WORK SITE. 7 HRS.

24 OCT '01 EAST VEIN
DRILLED HOLES AND WEDGED
OUT ORE. 6 HRS.

25 OCT '01 EAST VEIN
DRILLED HOLES AND WEDGED
OUT ORE AND ROCK. WAS
INTERVIEWED BY A TV NEWS
CREW AND WAS FILMED WHILE
DRILLING. 7 HRS.

26 OCT '01 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE. 7 HRS.

--- 47 HR-- CARRY 7 OVER TO
NEXT WEEK.

29 OCT '01

EAST VEIN

SCALED LOOSE IN THE CAP MAGAZINE
AND SHAFT STATION AREA. DRILLED
HOLES AND WEDGED OUT ORE. 7 HRS.

30 OCT '01

EAST VEIN

WEDGED OUT HOLES LEFT OVER FROM
MONDAY. DRILLED A NEW SET OF
HOLES AND WEDGED OUT SOME OF
THEM. 6 HRS.

31 OCT '01

EAST VEIN

WEDGED OUT A LOAD OF ORE.
USED THE EIMCO TO CLEAN UP
THE WORK SITE AND LOOSEN UP
A LARGE BLOCK OF ORE. 4 HRS.

1 NOV '01

EAST VEIN

WRAPPED A CHAIN AROUND THE BIG
BLOCK OF ORE AND USED THE EIMCO
TO MOVE IT OUT OF THE WAY. BOB
WILL USE HIS LOADER TO MOVE IT TO
THE RAINBOW TUNNEL. DRILLED HOLES
AND WEDGED OUT ORE. LOADED FOUR
DRUMS OF ROCKS ON A TRUCK.
6 HRS.

2 NOV '01

EAST VEIN

MOVED SOME OBSTACLES AND
PUT THE BIG BLOCK IN THE
RAINBOW ROOM. IT LOOKS GREAT,
WEDGED OUT ORE. HAD A VISIT
FROM A BIG GROUP OF GEOLOG-
OGISTS ON FIELD TRIP. 7 HRS.

5 NOV '01

EAST VEIN

HAND MUCKED CORRODED ROCK OFF
THE NORTH END OF THE WORK
SITE. DRILLED HOLES AND WEDGED
OUT ORE. 6 HRS.

7 NOV '01

EAST VEIN

WEDGED OUT ORE. DRILLED
HOLES IN F/W ROCK AND
WEDGED THEM OUT. HAND
MUCKED FINE ROCK. GOT
TOGETHER STUFF TO PUT
IN TWO ROCK BOLTS.
6 HRS.

9 NOV '01

EAST VEIN

MOVED A SCALE CLOSE TO THE ORE
HEAP. PUT IN TWO 8' BOLTS, DRILLED
HOLES WITH THE NEW BIG BIT AND
WEDGED OUT ORE. 6 HRS.

- - - 55 - - -

12 NOV '01 EAST VEIN
WEDGED OUT ORE. DRILLED A NEW
SET OF HOLES. 7 HRS.

13 NOV '01 EAST VEIN
WEDGED OUT ORE. DRILLED A NEW
SET OF 18 HOLES. 7 HRS.

14 NOV '01 EAST VEIN
WEDGED OUT MOST OF THE HOLES
THAT WERE DRILLED TUESDAY. 7 HRS.

15 NOV '01 EAST VEIN
FINISHED WEDGING OUT THE LAST
SET OF HOLES. DRILLED A NEW SET.
WILL BE LEAVING A BIG PIECE OF
ORE IN THE MIDDLE OF THE WORK
SITE. I HOPE IT WILL COME OUT
IN ONE PIECE. 6 HRS.

19 NOV '01 EAST VEIN
WEDGED OUT ORE. HAD TO DRILL SOME
RELIEVERS TO GET IT TO BREAK.
7 HRS.

20 NOV '01 EAST VEIN
WEDGED OUT ORE. DRILLED A NEW SET
AND WEDGED OUT SOME OF THEM.
5 HRS.

21 NOV '01

EAST VEIN

WEDGED OUT ORE. USED THE EIMCO TO MOVE A 1/2 TON COPPER SLAB TO THE MUSEUM. THEN BOB AND I HAD TO MANHANDLE IT THRU THE DOOR. IT IS FROM THE CHIMNEY ROCK QUARRY AND IS COVERED WITH CHRYSOCOLLA. A SMALL PIECE FELL OFF AND I GRABBED IT. MOVED TOM WARREN'S DESK TO THE GTC. BY THAT TIME THE EIMCO WAS HOT AND WOULD BARELY MOVE. 7 HRS.

--- 46 ---

26 NOV '01

EAST VEIN

WEDGED OUT ORE. DRILLED A NEW SET OF HOLES AND WORKED ON THEM. WAS ABLE TO GET THE EIMCO INSIDE FOR OVERNITE WARM STORAGE. 7 HRS.

27 NOV '01

EAST VEIN

WEDGED OUT ORE. DRILLED A NEW SET OF HOLES AND WEDGED THEM OUT. TRYING TO FREE UP ANOTHER LARGE BLOCK. 7 HRS.

28 NOV '01

EAST VEIN

WEDGED AND PRIED OUT ORE SOUTH OF THE BIG PIECE. DRILLED HOLES AND WEDGED & PRIED OUT ORE NORTH OF THE PIECE. CLEANED OUT THE CRACK BEHIND THE PIECE. ATTACHED A CHAIN. 6 HRS.

29 NOV '01

EAST VEIN

SCALED LOOSE IN THE RAINBOW TUNNEL. STOOD BY UNTIL A TRUCK ARRIVED AND LOADED 3 DRUMS OF ROCK. THIS WAS THE BOSTWICK DEAL. MANAGED TO MOVE THE BIG PIECE BUT THE EIMCO COULD NOT PICK IT UP. DRILLED A HOLE AND INSTALLED A 3' ROCK BOLT. BOB PUT A CHAIN ON THE BOLT AND USED HIS LOADER TO MOVE IT. 6 HRS.

30 NOV '01

EAST VEIN

CLEANED UP THE CHUNKS AND DEBR LEFT IN THE HOLE. DRILLED A NEW SET OF HOLES IN A NICE PIECE OF ORE. IT WAS BEHIND THE PIECE. WEDGED OUT ORE. 6 HRS.

3 DEC '01 EAST VEIN
FINISHED WEDGING OUT THE
LAST SET OF HOLES. HAD TO
PULL A FEW CHUNKS OUT OF THE
HOLE WITH THE EIMCO. 5 HRS.

4 DEC '01 EAST VEIN
DRILLED THREE TEST HOLES TRYING
TO FIND THE STOPE. NO LUCK. MOVED
THE DRILL TO THE TOP OF THE OUTCROP
NEAR THE ZINCITE BAND. DRILLED A
NEW SET OF HOLES AND WEDGED OUT
A FEW. 5 HRS.

5 DEC '01 EAST VEIN
DRILLED HOLES AND WEDGED
OUT ORE. IT IS NOW ZINCITE
RICH. HANDMUCKED DEBRIS OFF
THE OUTCROP. 5 HRS.

6 DEC '01 EAST VEIN
WEDGED AND PRIED OUT ORE.
HANDMUCKED WASTE ROCK OFF THE
OUTCROP. DRILLED A NEW SET OF
HOLES AND WEDGED THEM OUT. 5 HRS.

- - - 52 - - -

10 DEC '01 EAST VEIN
SCALED LOOSE IN THE RAINBOW
TUNNEL. WEDGED AND PRIED OUT
ORE. HANDMUCKED THE OUTCROP.
TRIED TO DRILL A NEW SET OF
HOLES. THE GROUND IS CRACKED
UP AND BEGAN TO SHIFT. PRIED
OUT BIG PIECES. WASHED OFF THE
OUTCROP TO GET RID OF SLIPPERY
MUD. 7 HRS.

11 DEC '01 EAST VEIN
SCALED LOOSE NEAR THE RAINBOW
ROOM. PRIED A LOT OF LOOSE ORE
OFF THE OUTCROP. REMOVED TWO
ROCK BOLTS (PUT IN NOV, 9) BUT
THE BIG SLAB WONT MOVE. 7 HRS.

13 DEC '01 EAST VEIN
BOB FILLED IN THE HOLE THAT THE
GOOD ORE CAME OUT OF AND TRIED
TO MOVE THE BIG SLAB WITH HIS
LOADER. NO LUCK. HAND MUCKED
DIRT OFF THE FOOTWALL ZONE.
DRILLED A SET OF HOLES IN ORE,
PYROXENE ZONE AND GNISS ZONE.
4 HRS.

18 DEC '01 EAST VEIN
WEDGED OUT GNEISS, CALC SILICATE
AND ORE. FOUND A ZONE THAT
SHOWS POTENTIAL FOR GARNET
AND GARNITE XLS. 6 HRS.

19 DEC '01 EAST VEIN
WEDGED OUT ORE. HAND MUCKED
DIRT OFF THE OUTCROP. DRILLED
HOLES IN GNEISS AND CALC SILICATE.
7 HRS.

20 DEC '01 EAST VEIN
WEDGED OUT ROCK. USED THE
EIMCO AND A SHOVEL TO CLEAN OFF
MORE OF THE OUTCROP. HELPED
UNLOAD FOUR SKIDS OF BOXES FOR
ROCK DISCOVERY. 7 HRS.

--- 38 ---

26 DEC '01 EAST VEIN
DRILLED A NEW SET OF HOLES IN
ORE AND CALC SILICATE. WEDGED
OUT SOME ORE. 4 HRS.

27 DEC '01

EAST VEIN

SCALED LOOSE IN THE EDISON AND
LANDMESSER TUNNELS. WEDGED
OUT ORE AND ROCK. 4 HRS.

3 JAN '02

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE.
CREATED A SLOT NORTH OF A VERY LARGE
PIECE OF ORE. (TEPHROITE AND FRANKLINITE
IN CALCITE) 3 HRS.

4 JAN '02

G. T. C.

MOVED THE COMPRESSOR TO THE
SOUTH END OF THE G. T. C. SET
UP THE "53" AND DRILLED HOLES
IN CONCRETE. BEGAN WEDGING
OUT A TROUGH IN THE BRIDGE
AT THE SOUTH END OF THE
G. T. C. WATER RUNNING OFF
THE NEW ROOF HITS THE
BRIDGE AND RUNS BACK UNDER
THE ROOF. 3 HS.

---14 HRS---

10 JAN '02

G. T. C.

DRILLED HOLES AND WEDGED OUT
CONCRETE, AFTER SHOVELLING
SNOW OFF THE WORK SITE. 5 HRS.

14 JAN '02

G. T. C.

DRILLED HOLES AND WEDGED OUT
CONCRETE. 5 HRS.

15 JAN '02

G. T. C.

DRILLED HOLES AND WEDGED OUT
CONCRETE. THE TROUGH IS DONE.
MOVED THE DRILL TO THE DRIVE-
WAY. DRILLED HOLES IN A CONCRETE
COLUMN BASE AND WEDGED IT
APART. THIS WILL MAKE IT EASIER
TO GET AROUND A SHARP TURN
IN THE DRIVEWAY. 4 HRS.

16 JAN '02

G. T. C.

CLEANED UP CONCRETE DEBRIS
AND DUMPED IT IN THE FILL QUARRY.
1.5 HRS.

--- 15.5 ---

5 FEB '02

G.T.C.

JOHN GUMBS BUILT A NEW PARTITION
IN THE AUDITORIUM. I PINNED
IT TO THE CONCRETE. 2 HRS.

12 FEB '02

G.T.C.

BEGAN WORKING ON CONDUIT AND
JUNCTION BOXES FOR NEW FIRE
AND SECURITY ALARM SYSTEM.
7 HRS.

13 FEB '02

G.T.C.

WORKED ON NEW ALARM SYSTEM.
7 HRS.

14 FEB '02

G.T.C.

WORKED ON ALARM SYSTEM. FINISHED
THE MAIN NORTH-SOUTH 1" CONDUIT.
STARTED ON THE EAST-WEST 3/4"
BRANCH LINES. 7 HRS.

15 FEB '02

G.T.C.

WORKED ON NEW ALARM SYSTEM.
FINISHED NORTH ROOM. 7 HRS

--- 30 ---

18 FEB '02

G. T. C.

WORKED ON ALARM SYSTEM. 7 HRS.

19 FEB '02

G. T. C.

WORKED ON NEW ALARM SYSTEM.

I AM IN THE ROOM 2ND FROM THE SOUTH SIDE. LEATHEN DROPPED IN AND LOOKED OVER THE JOB.

7 HRS.

20-02-02

G. T. C.

FINISHED THE CONDUIT AND JUNCTION BOXES FOR THE ALARM SYSTEM. INSTALLED THE NEW LENSES ON THE FLUORESCENT LIGHT FIXTURES. 7 HRS.

--- 21 ---

19 MAR '02

WEST VEIN

ROWETT, THE CONTRACTOR THAT RENTS THE UPPER YARD, IS USING A BACKHOE TO FACE THE RAMP TO THE GRIZZLY TUNNEL WITH BOULDERS. HE NEEDS MORE THAN WHAT WE GOT OUT OF THE W/V SLOPE SO HE TOOK SOME OFF THE TOP OF THE SLOPE. HE DUG BACK UNTIL THERE WAS A HIGH SCARP OF ROCKS.

I HAD TO USE A LONG BAR
AND PIPE TO GET AN AVALANCH
TO COME DOWN. A HUGE ROCK
ROLLED OUT QUITE A WAY.

1.5 HRS.

25 MAR '02 WEST VEIN

GOT MORE BIG ROCKS TO ROLL
DOWN. 2 HRS.

29 MAR '02 EAST VEIN

CLEANED OFF THE OUTCROP WITH
A BLOW PIPE. MOVED THE AIR
COMPRESSOR BACK TO THE EAST
VEIN. CARRIED THE DRILL AND TOOLS
TO THE EAST VEIN. BARRED OUT
MORE BOULDERS AT THE WEST
VEIN STOPE. 7 HRS.

--- 10.5 ---

1 APR '02 EAST VEIN

PUT WEDGES IN A ROW OF HOLES
I DRILLED IN JANUARY. SPLIT
A VERY LARGE SLAB BUT IT
WOULD ONLY MOVE ABOUT ONE INCH.
WASHED OFF THE OUTCROP.

DRILLED HOLES AND WEDGED OUT
ORE (RED & GREEN). 7 HRS.

2 APR '02 EAST VEIN

REPAIRED A LEAK IN THE WATER PIPE IN THE EDISON TUNNEL.

WEDGED OUT THE LAST SET OF HOLES. DRILLED A NEW SET AND WEDGED OUT SOME OF THEM. 7 HRS.

3 APR '02 EAST VEIN

WEDGED OUT ORE. DRILLED A NEW SET OF HOLES. 7 HRS.

4 APR '02 EAST VEIN

WEDGED OUT ORE. AS I MOVE TO THE SOUTH THE ORE DIVES UNDER CALC SILICATE. MOVED THE EIMCO TO THE GIFT SHOP AFTER LUNCH TO BE READY TO UNLOAD A TRUCK. WHEN THE TRUCK GOT HERE THE STARTER ON THE EIMCO BROKE. THE TRUCK DRIVER WAS ABLE TO MANEUVER THE SKID ONTO HIS POWER TAIL GATE. 7 HRS.

8 APR '02

EAST VEIN

ROWETT USED A BACKHOE TO PULL OUT THE BIG PIECE I SPLIT ON APR 1ST. THIS THREW MUCK ON MY WORK SITE THAT HAD TO BE HAND MUCKED OFF. DRILLED HOLES AND WEDGED OUT ORE. MET OUR INSURANCE LADY TO SIGN PAPERS TO CHANGE TO A NEW HMO. 7 HRS.

10 APR '02

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE. A PHOTOGRAPHER TOOK PICTURES OF RON MISHKIN AND ME FOR A NEWSPAPER ARTICLE. 7 HRS.

11 APR '02

EAST VEIN

WEDGED OUT ORE. DRILLED A NEW SET OF HOLES AND WEDGED OUT SOME OF THEM. I AM USING A WHEELBARROW TO MOVE THE ORE TO A STORAGE PILE. 7 HRS.

12 APR '02

EAST VEIN

WEDGED OUT ORE. HANDMUCKED FINES OFF THE OUTCROP. DRILLED A NEW SET OF HOLES. 7 HRS.

--- 56 HRS ---

15 APR '02 EAST VEIN
WEDGED OUT ORE. 7 HRS.

17 APR '02 EAST VEIN
WEDGED OUT ORE. TRIED OUT
OUR NEW BUTTON BITS AND
2' WEDGE. BOTH WORK OK
7 HRS. VERY HOT TODAY.

18 APR '02 EAST VEIN
DRILLED HOLES AND WEDGED
OUT ORE. 7 HRS.

22 APR '02 EAST VEIN
WEDGED OUT ORE. MOVED THE DRILL
TO THE LOG CABIN SHAFT. SET UP
AND DRILLED HOLES IN A CONCRETE PIER.
WEDGED OUT SOME OF THEM. THIS WILL
MAKE IT EASIER TO DUMP FILL IN THE
SHAFT. 7 HRS.

24 APR '02 EAST VEIN
WEDGED OUT THE REST OF THE
CONCRETE PIER. MOVED THE
DRILL BACK TO THE EAST VEIN.
GOT A BLACK PLASTIC SHEET AND
CHECKED THE OUTCROP FOR
FLUORESCENCE. DRILLED A NEW
SET OF HOLES. 5.5 HRS.

25 APR '02

EAST VEIN

WEDGED OUT ORE. WORKED IN RAIN MOST OF THE MORNING. QUIT AT NOON TO GOT TO CHRIS BENTE'S WEDDING IN TANNERSVILLE. 4 HRS.

26 APR '02

EAST VEIN

WEDGED OUT ORE. SCALED AND PRIED SOME LOOSE ROCKS OFF THE OUTCROP. HAD TO DRILL AND BREAK THEM TO GET THEM OUT OF THE HOLE. HANDMUCKED DIRT OFF THE DRILL SITE. DRILLED A NEW SET OF HOLES. HIT A CRACK AT THE BOTTOM OF TWO HOLES AND BOTH MY NEW BITS ARE STUCK. 7 HRS.

--- 44.5 HRS ---

29 APR '02

EAST VEIN

WEDGED OUT ORE. MANAGED TO RETRIEVE BOTH BITS. 7 HRS.

30 APR '02

EAST VEIN

WEDGED OUT ORE. HAD TO DRILL SOME OF THE PIECES TO GET THEM OUT OF THE HOLE. ALSO DRILLED SOME RELIEVERS. 7 HRS.

1 MAY '02

EAST VEIN

WEDGED OUT ORE. HANDMUCKED DIRT OFF THE OUTCROP. DRILLED A NEW SET OF HOLES. WEDGED OUT A FEW. 5 HRS.

6 MAY '02

EAST VEIN

WEDGED OUT ORE. SCALED DOWN OVERHANGING ROCKS INTO THE HOLE THAT HAS BEEN EXCAVATED. MOVED 20' NORTH AND HANDMUCKED DIRT OFF THE OUTCROP. 7 HRS.

7 MAY '02

EAST VEIN

DRILLED HOLES AND WEDGED OUT ORE. BOB REMOVED A LARGE AMOUNT OF FILL WITH HIS LOADER. THIS FILL HAD BEEN USED TO COVER A RAISE FROM THE EAST VEIN STOPE. NOW I CAN EASILY GET AT THE ORE. 7 HRS.

8 MAY '02

EAST VEIN

BOB FINISHED MUCKING OUT THE FILL. I FINISHED UP WITH A SHOVEL. DRILLED HOLES AND WEDGED OUT ORE. 7 HRS.

9 MAY '02 EAST VEIN
DRILLED HOLES AND WEDGED OUT
ORE. DRILLED ANOTHER SET OF
HOLES AND WEDGED SOME OUT.
7 HRS.
---47---

14 MAY '02 EAST VEIN
DRILLED HOLES AND WEDGED OUT ORE.
HAVE TO HAND MUCK THE ~~ORE~~ OUTCROP
WHENEVER I DRILL A NEW SET OF
HOLES. 7 HRS.

15 MAY '02 EAST VEIN
DRILLED AND WEDGED TWICE.
7 HRS.

16 MAY '02 EAST VEIN
WEDGED OUT A FEW HOLES LEFT OVER
FROM WEDNESDAY. SPENT HOURS HAND
MUCKING TO EXPOSE ORE. DRILLED 25
NEW HOLES. 7 HRS.

17 MAY '02 EAST VEIN
WEDGED OUT LOTS OF NICE ORE.
7 HRS.

20 MAY '02 EAST VEIN
WEDGED OUT HOLES DRILLED ON
THURSDAY. DRILLED 3 MORE
FROM A DIFFERENT ANGLE AND
WEDGED THEM OUT. DRILLED
SOME RELIEVERS AT THE TOE.
7 HRS.

21 MAY '02 EAST VEIN
BOB GOT A NEW STARTER FOR THE
EIMCO FROM A RECENTLY CLOSED MINE
IN BALMAT, N.Y. HAD TO GRIND DOWN
THE NOSE TO FIT IT IN. HAD TO REPAIR
THE GRINDER. ALSO HAVE TO CHANGE OVER
TO A PUSH BUTTON START SYSTEM.
MAPPED OUT THE WIRING IN THE DISPLAY
EIMCO BECAUSE IT HAS A PUSH BUTTON.
DRILLED HOLES AND WEDGED OUT ORE.
7 HRS.

22 MAY '02 EAST VEIN
CHANGED OVER TO THE NEW START
SWITCH. THE EIMCO STARTED
BUT SOON QUIT. APPARENTLY
WATER IN THE FUEL TANK.
WEDGED OUT SOME ORE. THEN
HELPED LEATHAM INSTALL NEW
EXIT AND EMERGENCY LITES IN
THE GIFT SHOP. ALSO PULLED
WIRE FOR THE ALARM SYSTEM

IN THE GEO TECH CENTER. 7.5 HR.

23 MAY '02

EAST VEIN

WORKED ON GETTING WATER OUT OF THE FUEL SYSTEM ON THE EIMCO. ADDED AN EXTRA JUNCTION BOX FOR THE ALARM SYSTEM IN THE G.T.C. DRILLED HOLES AND WEDGED OUT ORE. TOOK SOME BETTER STUFF TO THE GIFT SHOP. 7 HR.

24 MAY '02

EAST VEIN

GOT THE EIMCO RUNNING BY PRIMING THE ~~FE~~ FUEL SYSTEM. WEDGED OUT ORE. 7 HRS.

---63.5---

28 MAY '02

EAST VEIN & G.T.C.

FINISHED WEDGING OUT LAST SET OF HOLES. INSTALLED CONDUIT AND FOUR JUNCTION BOXES FOR NEW ALARM SYSTEM. 7 HRS.

29 MAY '02

EAST VEIN

FINISHED THE CONDUIT AND JUNCTION
BOXES IN THE G.T.C. HAND MUCKED
TO UNCOVER MORE OF THE ORE. GOT
AN EIMCO LOAD. DRILLED HOLES AND
WEDGED OUT ORE. 7 HRS.

3 JUN '02

EAST VEIN

DRILLED HOLES AND WEDGED OUT
ORE. 7 HRS.

4 JUN '02

EAST VEIN

DRILLED, WEDGED, HAND MUCKED.
7 HRS.

5 JUN '02

EAST VEIN

DRILLED HOLES IN ORE AND A NEARBY
REALGAR OCCURANCE. WEDGED OUT ORE.
7 HRS.

6 JUN '02

EAST VEIN

WEDGED OUT ORE AND REALGAR.
7 HRS.

7 JUN '02

EAST VEIN

WEDGED, HAND MUCKED, DRILLED,
HAND MUCKED AND WEDGED OUT ORE.
7 HRS

- - - 49 - - -

10 JUN '02

EAST VEIN

DUG HOLES IN THE FLOOR OF
THE GLORY HOLE GRIZZLY DRIFT.
STEVE PHILLIPS IS INSTALLING
A STEEL SECURITY GATE.

WEDGED OUT ORE. BOB BROUGHT
IN A LARGE BEACH UMBRELLA
I CAN USE FOR SHADE. 7 HRS.

11 JUN '02

EAST VEIN

WEDGED OUT ORE. USED A CHAIN
AND THE EIMCO TO PULL BIG
~~PIECES~~ PIECES OUT OF THE HOLE.

WENT TO A MEETING WITH THE
COMPANY WHO WROTE OUR NEW
MASTER PLAN. 7 HRS.

12 JUN '02

EAST VEIN

FINISHED MOVING OUT THE BIG
PIECES, WEDGED OUT ORE.

DRILLED A NEW SET OF HOLES AND
WEDGED SOME OUT. 7 HRS.

13 JUN '02

EAST VEIN

WEDGED OUT ORE AND HAND
MUCKED WASTE OUT OF THE HOLE.

7 HRS.

14 JUN '02 G. T. C.
WORKED WITH LEATHAM AND
THE ALARM CO. INSTALLED 5
NEW JUNCTION BOXES AND
PULLED MORE WIRE. 7 HRS.

17 JUN '02 G. T. C. & E. V.
INSTALLED CONDUIT AND FOUR
MORE JUNCTION BOXES FOR
NEW ALARM SYSTEM. WEDGED
OUT ORE AT EAST VEIN. 7 HRS.

18 JUN '02 G. T. C. & E. V.
MADE AN ADJUSTMENT TO A
JUNCTION BOX. HAND MUCKED A
BUCKET LOAD OF DIRT OFF THE
EAST VEIN. DRILLED PART OF
A SET OF HOLES IN ORE. 4 HRS.

19 JUN '02 EAST VEIN
FINISHED DRILLING A SET OF
HOLES. WEDGED OUT ORE. 7 HRS.

20 JUN '02 EAST VEIN
WEDGED OUT ORE. 7 HRS.